

TORQUE TRANSMITTING APPARATUS  
Gunnar BACK, et al.  
Docket No. 3191/11393-US1




Fig. 1





Fig. 2






Fig. 4




Fig. 5




Fig. 6

6/18




Fig. 7

7/18




Fig. 8

8/18




Fig. 9

Fig. 10

Fig. 11

Fig. 12




Fig. 13




Fig. 13a




Fig.14




Fig.15

10/18




Fig. 16a




Fig. 16b




Fig. 17a




Fig. 17b




Fig. 18a




Fig. 18b

TORQUE TRANSMITTING APPARATUS  
Gunnar BACK, et al.  
Docket No. 3191/1I393-US1




Fig. 19a




Fig. 19b




Fig. 20a




Fig. 20b

12/18




Fig. 21




Fig. 22




Fig. 23




Fig. 24

13/18





Fig. 26




Fig. 27




Fig. 25




Fig. 28

14/18




Fig. 29a




Fig. 29b




Fig. 29c




Fig. 29d




Fig. 29e




Fig. 29f




Fig. 29g




Fig. 29h




Fig. 29i




Fig. 29j





Fig. 29k

15/18



16/18




Fig. 31




Fig. 32a




Fig. 32b

17/18




Fig. 33




Fig. 34a




Fig. 34b




Fig. 35